

Federal Recalls

No.	Description	Supplier	Release Date
10KWD	Recall 10KWD - DV-2 Air Governor Breather Missing	Kenworth Truck Company	6/3/2010
10KWC	Recall 10KWC C500 Hood Bracket Interference with Steer Axle Brake Chambers	Kenworth Truck Company	6/2/2010
10KWB	Recall 10KWB Low Rear Outer End Hub Oil	Kenworth Truck Company	5/19/2010
10KWA	Recall 10KWA Over-torque of Non-LMS Hubs	Kenworth Truck Company	4/21/2010
09KWB	09KWB Steering Gear Mounting Fastener Torque	Kenworth Truck Company	12/23/2009
09KWA	09KWA AG400L U-Bolt Torque	Kenworth Truck Company	10/28/2009
09KW8	Recall 09KW8 - TRW Steering Shaft Weld	TRW Automotive	8/5/2009
09KW7	Recall 09KW7 - Brake Assembly Cracking	Kenworth Truck Company	7/17/2009
09KW6	Recall 09KW6 - Steer Axle Brake Mounting Bolts Loose	Dana Axle	7/9/2009
09KW3	Recall 09KW3 - Rear Caliper Mounting Bolts	Kenworth Truck Company	6/5/2009
08KWB	Rear Brake Cam Tube Cracking on AG400 with Long-stroke Brake Chambers	Kenworth Truck Company	3/9/2009
08KW9	Recall 08KW9 - Airglide 380 U-Bolt Nut Torque	Kenworth Truck Company	8/4/2008
08KW8	T660 Headlight Harness Interference with Hood Latch	Kenworth Truck Company	7/14/2008
08KW7	Recall 08KW7 - T300/T270/T370 Fuel Line Interference	Kenworth Truck Company	6/24/2008
08KW6	Recall 08KW6 - Trailer Plug Bracket	Kenworth Truck Company	5/30/2008
08KW5	Recall 08KW5 - Holland Fifth Wheel Pivot Bolt	SAF-Holland	5/1/2008
08KW4	Recall 08KW4 - Pivot pin (bolt) in the Premier model 690 pintle hook	Premier Manufacturing Co	4/18/2008
08KW3	Recall 08KW3 - Bendix MV-3 Brake Valve	Bendix	4/8/2008
08KW2	Recall 08KW2 - Fabco Slack Adjusters on SISU Axles	Fabco	3/21/2008
08KW1	Recall 08KW1 - TriMark Door Latch	TriMark	3/6/2008
07KWF	Recall 07KWF - Eaton Synflex Air Brake Hose	Eaton Synflex	2/13/2008
07KWE	Recall 07KWE TRW TAS85 Steering Gear	TRW	1/3/2008
07KWA	07KWA Front Tow Hitch (07KA1 & 07KA2 in SIR)	Kenworth	8/28/2007
07KW8	Air Intake Grid Heater jumper wire can rub	Kenworth	7/11/2007
07KW7	Recall 07KW7 - T660 Horton Fan Blade	Horton	7/6/2007
07KW4	Dana Corporation's rear axle housings	Dana Corporation	6/12/2007
07KW9	Recall 07KW9 - C500 Hood Bracket-Brake Chamber Interference	Kenworth	6/8/2007
07KW6	Recall 07KW6 - Hood Safety Cable Too Long	Kenworth	6/6/2007
07KW5	07KW5 - Davco Fuel-Water Separator with Heater	Davco	6/5/2007
07KW3	07KW3 Allison Transmission Auto-Neutral Functionality	Kenworth	5/16/2007
07KW2	07KW2 PRIMAXX Rear Suspension Brake Timing	Kenworth	5/11/2007
07KW1	Phillips Trailer Light Line and Trailer Connection	Kenworth	4/9/2007
06KW4	06KW4 Cruise Control Pressure Sensor	Honeywell Hobbs	1/5/2007
06KW3	06KW3 Fifth Wheel King Pin Air Release Valve	Bachman Valve Corp.	12/22/2006
06KW2	06KW2 - TRW Telescoping Steering Column	TRW	12/14/2006
06KW1	Chalmers adjustable torque rod brackets may be weak.	Chalmers	11/2/2006
05KW6	Bendix ESP Recall	Bendix	4/14/2006
05KW5	T300 Bosch Parking Brake Recall	Bosch	10/24/2005
05KW4	AG460 Suspension Recall	Horikiri	6/15/2005
05KW3	Neway AD-XXX Rear Suspension Recall	Holland-Neway	6/3/2005
05KW2	Accuride 22.5 x 8.25 Aluminum Wheels not properly pre-stressed.	Accuride	5/20/2005
05KW1	Heater Burner Tube	Webasto	3/29/2005
04KW8	Power Feed Harness	Dynacraft	2/11/2005
04KW9	T2000 with L83-1000 Hood Lock Cylinder	Power Packer	1/20/2005
04KW7	BIII AeroCab LH Door Aperture Huck Bolts	M&J Welding	11/17/2004
04KW6	Driveline U-joint to Transmission Yoke Torque	Kenworth	11/3/2004
04KW5	Battery Box Support Brackets	Kenworth	9/10/2004
04KW4	Cummins Cylinder Block Boss Hole 04V-506	Cummins	9/3/2004
04KW3	Leece Neville Brushless Alternator with CAT C11/C13 Engine	Leece Neville	8/20/2004
04KW2	Door Sticker Tire Pressure Omitted	Kenworth	8/4/2004
04KW1	Ultrashtif Transmission Wiring	Eaton Fuller	5/5/2004
03KWH	Fan Hub Bolts Loosen	Horton	4/20/2004
02KW5	Engines 3126E	Caterpillar	1/15/2004
03KWA	Front Axle Integral Knuckle and Steer Arm Assembly	Dana	12/22/2003
03KW9	Fan Hub Bolts Loosen	Kenworth	12/3/2003
03KW7	Battery Mounted Circuit Breaker	Kenworth	10/8/2003
03KW8	Hub Retaining Nuts T300	Kenworth	8/22/2003

Federal Recalls

No.	Description	Supplier	Release Date
03KW4	Fifth Wheel Bracket Pin	Jost	7/23/2003
03KW5	Frame Access Grab Handle	Kenworth	7/15/2003
03KW6	Electronic Control Module	Cummins	7/9/2003
03KW2	Steer Axle Hubs FF981	ArvinMeritor / SKF	5/9/2003
03KW3	P 18x7 Brakes	Meritor	5/7/2003
03KW1	Trailer Light Cords	Phillips	4/18/2003
02KW4	Trailer Control Hand Valve TC-7	Bendix	1/29/2003
01KW8	Tie Rod Ball Sockets	TRW	8/20/2002
02KW3	Drive Axle Reweld	Dana Spicer	6/17/2002
02KW2	Power Distribution Box	AFL	2/15/2002
02KW1A	ABS Valve	Meritor Wabco	2/15/2002
01KWB	Front Hubs	ArvinMeritor / SKF	11/30/2001
01KWA	U-Joint Bolt Torque	Kenworth	11/9/2001
01KW9	HVAC Mode Control Door	Bergstrom	11/2/2001
01KW7	Tie Rod Ends	Dana	10/8/2001
01KW5	Torque Rods 800 Series Suspension	Chalmers	7/20/2001
01KW6	Fire Service Vehicles	Kenworth	6/25/2001
01KW4	FG941 Axle Ratings	Meritor	6/15/2001
01KW3	Steering draglinks	TRW	5/18/2001
01KW2	Airglide 200 Lower Sway Arm	Kenworth	3/15/2001
01KW1	Wiring at Firewall-Mounted Circuit Breaker	Kenworth	2/16/2001
00KW3	Tie Rod Ball Sockets	TRW	10/17/2000
00KW1	Brake Valve	Bendix	2/18/2000
99KW5	Hubs	Meritor \ SKF	12/22/1999
99KW4	Aluminum Steering Driveline	Dana	11/19/1999
99KW2	Front Axle Hubs	Meritor / SKF	6/18/1999
99KW1	Slack Adjusters	Meritor	5/25/1999
98KW1	3406E Engines	Caterpillar	6/29/1998
97KW3	Steer Axle Hubs	Meritor	12/15/1997
97KW2	AG200 Swaybar Arm Assembly	Kenworth	8/15/1997
97KW1	T2000 Door Latch	Kenworth	6/30/1997
96KW1	Signal-Stat Turn Signal Switch	Federal Mogul	4/15/1996
DAAO	Glad-Hands	Phillips Industries	12/15/1995
DAAM	Front Steer and Steerable Pusher Axles	Rockwell	7/26/1995
DAAN	Air Cushion II Reclining Seats	Bostrom	6/2/1995
DAAL	Air Dryers	Rockwell Wabco	3/27/1995
DAAK	Seat Belt on 74" Studio Sleeper	Kenworth	5/31/1994
DAAJ	Air Dryer	Midland-Grau	4/11/1994
DAAH	Steering Gears	RH Sheppard	12/6/1993
DAAG	Pitman Arm Pinch Bolt Torque	Kenworth	3/15/1993
DAAD	Electronic Accelerator with Detroit DDEC	Williams Controls	1/20/1993
DAAF	Front Steer Axle U-Bolt	Kenworth	1/8/1993
DAAD	Electronic Accelerator with Detroit DDEC	Williams Controls	11/15/1992
CAAU-B	Front Axle Steering Arm	Rockwell	9/23/1992
DAAC	Electronic Accelerator with Cummins Celect	Williams Controls	9/15/1992
DAAA-A	Brake Chambers	MGM Brakes	7/6/1992
DAAA	Brake Chambers	MGM Brakes	7/6/1992
CAAW	Engine Fan	Flex-A-Lite	10/18/1991
CAAY	Wiper Pivot Assemblies	Sprague	9/23/1991
CAAZ	Steering Gears	TRW	9/23/1991
CAAX	ABS Brake Timing	Bosch	6/15/1991
CAAT	Airglide 100 Suspension Stabilizer Bars	Kenworth	6/5/1991
CAAV	Air Suspension Spring Hangers	Hendrickson	5/29/1991
CAAQ	Pitman Arm Pinch Bolt Torque	Kenworth	6/27/1990
CAAP	Fuel Line Routing	Cummins	11/14/1989
CAAJ	Cruise Control	Bendix	9/27/1989
CAAA	Front Steer Hub Hardness	Kenworth	1/5/1987